

# DERMASAYER CASE STUDY

## CASE STUDY

PEACHTREE CENTRE, GAFFNEY, SC

### ■ BY AMANDA McABEE, RN

Resident has a very large skin tear on her right leg (approx. 10cm x 10cm and just this week received two shin-tears to her left leg (one approx. 1 inch and the other approx 6cm)

Nov 26 - The resident's skin tears have already scabbed over!



DERMASAYER FULL LEG TUBE

# 66417



DERMASAYER STAY-PUT  
HEEL PROTECTOR

# 66420



#### PRIMARY CARE STAFF:

PAT PUTNAM, LPN, INJECTION CONTROL  
NURSE; ANGE ACREY, LPN, FLOOR NURSE;  
APRIL CRAWFORD, LPN, FLOOR NURSE



Nov 28 - Resident already had a blister on her ankle, but with her thin skin condition, it opened up. So we started using the Stay-Put Heel Protector.

